




AFTER CARRYING OUT FIRST LEVELLING OF BEDS BY ACTING ON THE PREARRANGED SCREWS, POSITION TOOL AT845 ON THE TABLE BED LEADING GUIDE.

REGULATE HEIGHT AND LENGTH OF TOOL SO THAT THE COMPARATOR REACHES TO FEEL THE SURFACE TO BE CHECKED.

AT THIS POINT VERIFY PARALLELISM BY TRAVERSING THE TOOL HORIZONTALLY OVER THE ENTIRE SURFACE. THEN PROCEED TO FILLING THE FORMWORKS WITH RHEOPLASTIC MORTAR.

		COLGAR				
			DISEGN. WT	DATA 01/98		
DENOMINAZIONE			MODELLO	FOGLIO	MACCHINA-COMPL. PROGRAM 213TR12 DELAVAL	
PARALLELISM CHECKING SCHEME				3/7		F002691400